

DISTRIBUTION

FILE: CABLE SEC

OFFICE

OUT 6682

P 132354Z JAN 69 FM NPIC WASHDC TO RHCOAAA/SAC OFFUTT AFB OMAHA NEB RHCOAAA/544TH ARTW OFFUTT AFB OMAHA NEB RUCLFGA/120TH SRW OL 19 MCCOY AFB FLA RUWJDBA/100TH SRW DAVIS MONTHAN AFB ARIZ RUEBJRA/NAVRECONTECHSUPPCEN SUITLAND MD RUEAIIA/CIA WASH DC RUEOJFA/DIA RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF RUEFHQA/HQS USAF

S E C R E T CITE NPIC 5463.

SAC FOR DIR, DOSR, DISD; 15TH AF FOR DI. DO; 100TH SRW FOR CO, DCOI; HQ USAF FOR AFRDR DIA FOR DIAXX-2. FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

SUBJECT: EVALUATION OF GLASS LAMP MISSION G-062

1. IMAGE QUALITY: THE OVERALL IMAGE QUALITY OF THIS MISSIONPSCYOC IS FAIR. AN APPARENT SLIGHT OUT OF FOCUS CONDITION IS PRESENT RRD THROUGHOUT THE MISSION. THERE IS A NOTICEABLE CHANGE IN IMA<u>GE</u>

PP&BYAD SECUR. 25X1 TSSG/9/SDIC REPRO AID TEG SCILN DIA-XX4 SPAD DIA-AP

25X1

PAGE 2 RUEADJU Ø070 S E C R E T QUALITY ACROSS THE FORMAT; THE DATA BLOCK END OF FRANE IS POORE! THAN THE NOW-DATA END OF FRAME. INTERPRETATION SUITABILITY TO GOOD. CLOUD COVER AND HAZE OBSCURE LESS THAN ONE PERCENT OF THE CONTROL OF THE MISSION.

2. MISSION DATA:

A. GLASS LAMP MISSION G-062 WAS FLOWN ON 8 JANUARY

A STANDARD "B" CAMERA, UNIT 26, WAS EMPLOYED.

B. FILM TYPE 3401 WAS USED THROUGHOUT WITH A 1/360 EXPOSURE AT F/1D. THE OR SIDE WAS PROCESSED TO AN AVERAGE GAMMA 2.13; THE 9L SIDE WAS PROCESSED TO AN AVERAGE GARNA OF 2.18. PROCESSING WAS ACCOMPLISHED BY WAV RECONTECH SUPPCEN.

3. ORIGINAL NEGATIVE:

A. THE MATERIAL APPEARS TO BE SLIGHTLY OVEREXPOSED FOR SANITIZED APPROXIMATELY THE LAST 400 FRAMES. WITH TEXT

B. DENSITY AND CONTRAST APPEAR TO BE GENERALLY MEDIUM; HOWEVER, THE LAST 400 FRAMES ARE MORE DENSE AND OF HIGHER CONTRAST.

C. ILAGE DEGRADATIONS:

(1) 9R SIDE: PLUS DENSITY AREAS, ASSOCIATED WITH ROLLER CHATTER ARE PRESENT ALONG THE INBOARD EDGE. THESE AREAS INCREASE IN DENSITY AND FREQUENCY AS THE MISSION PROGRESSES. LIGHT LEAK INDUCED

PAGE 3 RUEADJU 2270 S E C R E T

FOG IS PRESENT ALONG THE DATA BLOCK EDGE OF FRAME 778.

(2) 9L SIDE: EDGE STATIC AND ROLLER CHATTER ARE PRESENT ALONG THE INBOARD EDGE FOR APPROXIMATELY THE FIRST 350 FRAMES. TWO. THIN PLUS DENSITY STREAKS, PARALLEL TO THE MAJOR AXIS AND 4.5 INCHES FROM THE OUTBOARD EDGE, ARE PRESENT ON THE FILM FROM FRAME 298 TO THE END OF THE MISSION.

D. PHYSICAL DEGRADATIONS:

(1) 9R SIDE: EMULSION SCRATCHES C.1 INCHES LONG. SPACED S.3 INCHES APART, ARE PRESENT IN FRANES 433-458 APPROXIMATELY 0.7



Excluded from automati downgrading and declassification



INCHES FROM THE FILM OUTBOARD EDGE. FOREIGN MATTER IS PRESENT IN FRAME 449.

- (1) 9L SIDE: NONE NOTED. E. AUXILIARY DATA: ALL DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY.
- F. OTHER: THE LAST TITLED FRAME IS 779.
 4. POSITIVES: THE QUALITY OF THE PRINTING AND PROCESSING IS
- ADEQUATE FOR READOUT PURPOSES.

 5. REWARKS: THE MISSION WAS ABORTED AFTER APPROXIMATELY 45
 PERCENT OF THE PLANNED ROUTE HAD BEEN COVERED. GP-1

SECRET .

END OF MESSAGE